## APPENDIX 5

## Tarek Ball

From: **Louise Perrins** 

Sent: 20 December 2019 12:34

 $\ddot{\circ}$ 

Subject: Env Svs Support Unit Your ref TB/TPO (6) 2019 Holm Oak to the front of 2, Milton Drive, Hagley

Attachments: 2 Milton Drive, Hagley, DY9 9LS.DOC; ATT00001.txt

Categories: Angela

This email originated from outside of the Organisation

STOP: Were you expecting this Email? Does it look genuine? THINK: Before you CLICK on links or OPEN any attachments.

outside our property following blockages that caused raw sewage to flow past our front door on two occasions this Please find below a letter from Severn Trent confirming that tree roots have had to be removed from sewage pipes



Severn Trent Water Limited
Cheltenham Road East
Gloucester
GL2 9QY

2 Milton Drive Hagley DY9 9LS

20/12/2019

## **Dear Mrs Perrins**

As per our phone conversation please see below the relevant information you requested

On the 31st October 2019 we received feedback on a blockage job indicating a manhole chamber was surcharged upon inspection, in which a blockage was then cleared with the cause being root ingress, these roots were then removed to prevent, as best as possible, the repeat issue of blockages occurring.

coming from the large tree not far from the manhole cover as this is above where the roots were identified causing an issue to the sewer. To clarify, the root cause of the blockages has been due to the roots, and these roots appear to be

Yours sincerely

Brandon Smith Senior Network Technician